Gold King Mine



While visit

Overview

Weather
Altitude
Mine Operations
Site Hazards
Wildlife
Heavy Equipment

- OPPE
- Special Instruction



Cold nights at or below freezing
Warm daytime temperatures of 80-90's
Wearing several layers of clothing provides
better insulation in cold
Shed layers as daytime temps warm up

Storms and Inclement Weather

Seek shelter immediately



Altitude Sickness

- Headache
 Loss of appetite
 Stomach ache or vomiting
 Loss of energy
- Insomnia
- Dizziness



Mine Operations

Treat and Sample discharge at site
Stabilize and maintain mine road
Refine water treatment process
Prepare to manage water treatment sludge
Prepare to start repairs on waste dump

Site Hazards

- Slips Trips and Falls
 - Uneven and steady ground
- Sun Exposure
- Heavy Equipment
- Confined Space
- Dehydration

Wildlife

Snakes

Bears

Deer

Locals ...

Site safety officer

Heavy Equipment

Heavy equipment is being used to assist with the clean up effort.

Operators are working long shifts and may be fatigued and distracted

Watch out for will

o Maintain eye contact with the eserator

REQUIRED PPE

All visitors MUST have and wear the following:

Hard Hat
Safety Vest
Protective Eyewear
Safety Footwear

Special Instruction:

All visitors are to follow the guidance of site OSC and/or designated site escort and don PPE prior to leaving the staging area.

All visitors must remain in the UTV at all times.

Ask The Safety Officer!

Safety is EVERYONE's Responsibility!

Current Safety Officers

Paul Hollar Personal Phone/Ex. 6

IMT Safety Officer – Montezuma County,
CO

Jason Nakatsu Personal Phone/Ex. 6
 IMT Safety Officer – US EPA Region 8